## HOW TO CARE FOR FORBES PRODUCTS

Type of Material	Recommended	Not Recommended
Wood Surfaces	Use a clean damp cloth (soft), immediately wipe off any moisture with a soft dry cloth.	Washing wood with soap and water may cause harm to the wood and/or the finish. The finish may become lusterless and lose some of the sheen.
	<ul> <li>Cleaning Agents:</li> <li>Pledge Furniture Polish</li> <li>Endust Cleaning &amp; Dust Spray</li> <li>Scott's Liquid Gold</li> <li>Old English Furniture Polish</li> <li>Behold Furniture Polish</li> <li>Murphy's 0il Soap / Spray Formula</li> <li>Kleen Guard Furniture Polish</li> </ul>	<ul> <li>Do Not Use:</li> <li>Lemon Oil</li> <li>Chlorine</li> <li>Bleaches</li> <li>Ammonias</li> <li>Windex <ul> <li>any solvent based cleaning or polishing</li> <li>products. Cleaning products with high</li> <li>concentrations of lemon oils.</li> </ul> </li> </ul>
High Pressure Laminate Surfaces	Use a mild soap with a clean Damp Cloth (soft), wipe off any soap residue and moisture with a soft dry cloth.	Do Not Use any solvent based cleaners or any abrasive cleansers or pads.
Countertops: Corian, Avonite and other hard surfacing materials	<ul> <li>To clean use a mild soap with a clean damp soft cloth making sure to wipe off any soap residue and moisture.</li> <li>DO NOT USE: Solvent based cleaning or abrasive cleaners or pads. Nicks and scratches can be repaired by a qualified Avonite Surfaces Fabricator. Please refer to Avonite's Care and Maintenance section on their website:</li> </ul>	Do not place any hot pans directly on surface. Avoid direct steam exposure. Keep surface free of moisture. Keep unit out of direct sunlight for extended periods of time. Don't use cutting utensils directly on surface. Avoid impact to surface. Anything harder than the countertop (i.e. ceramics, stoneware, stainless steel and glassware) may scratch the surface.



## HOW TO CARE FOR FORBES PRODUCTS

Type of Material	Recommended	Not Recommended
Stainless Steel	To clean use a mild soap with a clean damp soft cloth making sure to wipe off any soap residue and moisture.	Do Not Use any solvent based cleaners or any abrasive cleansers or pads.
Powder Coat Epoxy Finish	To clean use a mild soap with a clean damp soft cloth making sure to wipe off any soap residue and moisture.	Do Not Use any solvent based cleaners or any abrasive cleansers or pads.
Plastic Surfaces	<ul> <li>To clean use the following:</li> <li>Mild soap solution (eg, 5% lvory flakes in water)</li> <li>Mild detergent solution (eg, 3% Tide in water)</li> <li>Household ammonia</li> <li>25% isopropyl alcohol (isopropanol) in water</li> <li>"Simple Green" (diluted 1:10) if it is rinsed off promptly</li> <li>Turtle Hot Wax Protect All</li> <li>GM OptiKleen window wash (diluted)</li> <li>Mineral spirits</li> <li>Stain-Trine (Applied Biochemists, Mequon, WI) for mineral deposits .</li> <li>Speed Clean 100 (Applied Biochemists, Mequon, WI)</li> <li>Baking Soda (A gentle but effective abrasive for removing surface mars.)</li> </ul>	Do Not Use any solvent based cleaners or any abrasive cleansers or pads. Solvents such as MEK and Toluene, or Citrus or Pine based cleaners & disinfectants such as Lysol and Pine Sol should be avoided and not stored near the cart. Also Do Not Use • Concentrations of isopropanol greater than 25% • Most solvents including alcohols, esters and glycol ethers • Sherwin Williams' Aqua Mate • Vandal Mark Remover

Please contact us if you have any questions regarding the use of your Forbes Products.

Phone: (909) 923-4559 Fax: (909) 923-1969 Monday - Friday: 8 am - 5 pm

